

# WORK APPROVAL



Generated : 14-12-2025

<b>Claim Number</b>	<b>Insured Name</b>	<b>Workshop Name</b>
CLM000202512145161	OM DIXIT	RENEWAL MOSARAM

<b>Vehicle Number</b>	UP31BU9622	<b>Registration Year</b>	2022-02-04
<b>Chassis Number</b>	MBLHAW113MHE61066	<b>Odometer reading</b>	NIL
<b>Vehicle Manufacturer</b>		<b>Vehicle Model</b>	SPLENDOR PLUS
<b>Insurance Name</b>	The Oriental Insurance Company	<b>HUB Name</b>	NIL

S.NO	PARTS PARTICULAR	REPLACE/REPAIR	LABOUR	PAINTING
1	SIDE COVER LEFT	Replace	0	0
2	FUEL TANK REPAIR	Repair	1400.00	0
3	HANDLE PIPE	Replace	0	0
4	ACCIDENTAL LABOUR	Repair	250.00	0

S.NO	PARTS PARTICULAR
------	------------------

**Remarks**                      **Approval subjected to policy term and condition, 64VB confirmation and NCB confirmation and pre-inspection or previous claim photographs.**

**Note:**                              **\*\*Re-inspection is mandatory along with salvage.**  
**\*\* Approval is subject to policy terms & conditions**

**Approved By:**                      **Approver Contact No:**

**For MOTORSATHI SERVICES**

