

M/S RADHA MOTORS
 NEAR RANGILI MAHAL NANDGAON ROAD, BARSANA, MATHURA, 281405, UP, India
 State Code: 9 Contact: 9760116827, , ,
 GSTIN No: 09BJCPA7451D1ZK
 Associate Dealer: Hero MotoCorp Ltd.

ESTIMATE

Estimate No.	23850-02-REST-0126-47	Date	05-01-2026
Customer Name	RADHIKA GOSWAMI	Contact No.	7310811388
VIN	MBLJFW532PGE03801	Model	DESTINI 125
Insurance Company		Reg No.	UP85CL3280
HMCGL Card No		HMCGL Card Category	

S No	Part Number	HSN No.	Billing Type	Rate	Qty	SGST %	CGST %	UTGST %	IGST %	Discount %	Discount	Net Amount
1	64305ABS300VS -SET COVER FR. UPPER (MAT RAY SILVER)	87141090	Paid	1,171.19	1	9.00	9.00	0.00	0.00	0.00	0.00	1,382.00
2	64309ABS200VS -FRONT COVER LOWER	87141090	Paid	1,054.24	1	9.00	9.00	0.00	0.00	0.00	0.00	1,244.00
3	81131ABS3001S -COVER INNER PP BROWN	87141090	Paid	629.66	1	9.00	9.00	0.00	0.00	0.00	0.00	743.00
4	53205ABS300VS -COVER HANDLE FR MRS NH 437M	87141090	Paid	772.88	1	9.00	9.00	0.00	0.00	0.00	0.00	912.00
5	33100ABS301S -LIGHT ASSY HEAD	85122010	Paid	2,838.98	1	9.00	9.00	0.00	0.00	0.00	0.00	3,350.00
6	53209ABS300S -FR HANDLE COVER CHROME LH	87141090	Paid	175.42	1	9.00	9.00	0.00	0.00	0.00	0.00	207.00
7	61100ABS200VS -FRONT FENDER A ASSEMBLY NH-437M	87141090	Paid	1,190.68	1	9.00	9.00	0.00	0.00	0.00	0.00	1,405.00
8	6433AABS200VS -COVER L FLOOE SIDE SA MRS NH 437M	87141090	Paid	632.20	1	9.00	9.00	0.00	0.00	0.00	0.00	746.00
9	83400ABS300VS -SET L. BODY SIDE (MAT RAY SILVER)	87141090	Paid	1,780.51	1	9.00	9.00	0.00	0.00	0.00	0.00	2,101.00
Parts Total											0.00	12,090.00

Labour Details												
S No	Job Code	SAC No.	Billing Type	Rate	SGST %	CGST %	UTGST %	IGST %	Discount %	Discount	Net Amount	
1	102032 - ACCIDENTAL LABOUR-DESTINI 125	998729	Paid	850.00	9.00	9.00	0.00	0.00	0.00	0.00	1,003.00	
Jobs Total											0.00	1,003.00

Parts Total	12,090.00
Labour Total	1,003.00
SGST (Parts) 9%	922.12
CGST (Parts) 9%	922.12
SGST (Labour) 9%	76.50
CGST (Labour) 9%	76.50
Total	13,093.00

Rupees in Words: Thirteen Thousand Ninety Three Only

Authorised Signatory

1. Terms Cash
2. Prices & statutory levies prevailing at the time of delivery shall be charged
3. Vehicles in this workshop are handled/driven and kept at owner's risk.
4. Customers are requested to satisfy themselves with the quality of work done before taking the

23850 - Main W/S