

# WORK APPROVAL



Generated : 23-12-2025

<b>Claim Number</b>	<b>Insured Name</b>	<b>Workshop Name</b>
CLM000202512145205	BIPIN KUMAR	J P AUTOMOBILES (GUPTA AUTOMOBILE)

<b>Vehicle Number</b>	New	<b>Registration Year</b>	2025
<b>Chassis Number</b>	MBLHAW339SHGB1401	<b>Odometer reading</b>	NIL
<b>Vehicle Manufacturer</b>		<b>Vehicle Model</b>	SPLENDOR PLUS
<b>Insurance Name</b>	The Oriental Insurance Company	<b>HUB Name</b>	NIL

S.NO	PARTS PARTICULAR	REPLACE/REPAIR	LABOUR	PAINTING
1	FRONT VISOR	Replace	0	0
2	HEADLIGHT W/O BULB	Replace	0	0
3	HANDLE PIPE	Replace	0	0
4	GRIP-CARRIER	Replace	0	0
5	LEG GUARD	Replace	0	0
6	BRACKET PILLION STEP LEFT	Replace	0	0
7	MUFFLER COVER	Replace	0	0
8	GRIP REAR CARRIER) RH	Replace	0	0
9	MIRROR R	Replace	0	0
10	ACCIDENTAL LABOUR	Repair	424.00	0

S.NO	PARTS PARTICULAR
------	------------------

**Remarks**                      **Approval subjected to policy term and condition, 64VB confirmation and NCB confirmation and pre-inspection or previous claim photographs.**

**Note:**                              **\*\*Re-inspection is mandatory along with salvage.**  
**\*\* Approval is subject to policy terms & conditions**

**Approved By:**                      **Approver Contact No:**

---

**D-27, Shastri Nagar, Meerut, Utttar Pradesh, (250004) India**  
**Email ID:** info@motorsathi.com| **Mobile No.:**+91 79410 50643