WORK APPROVAL

Generated : 25-12-2025

Claim Number	Insured Name	Workshop Name
CLM000202512145419	RAHUL KUMAR	SB KHANDELWAL MOTORS

Vehicle Number	New	**Registration Year**	2025
Chassis Number	MBLHAW219RHM08214	**Odometer reading**	NIL
Vehicle Manufacturer	HERO MOTOCORP	**Vehicle Model**	SPLENDOR PLUS
Insurance Name	The Oriental Insurance Company	**HUB Name**	NIL

S.NO	PARTS PARTICULAR	REPLACE/REPAIR	LABOUR	PAINTING
1	ACCIDENTAL LABOUR	Repair	640.00	0
2	FUEL TANK REPAIR	Repair	1650.00	0
3	HANDLE PIPE	Replace	0	0
4	LEG GUARD	Replace	0	0
5	HEADLIGHT W/O BULB	Replace	0	0
6	FRONT VISOR	Replace	0	0
7	PANEL INNER	Replace	0	0
8	STAY HEAD LIGHT RH	Replace	0	0
9	STAY HEAD LIGHT LH	Replace	0	0
10	WINKER FR LEFT	Replace	0	0
11	FRONT FENDER	Replace	0	0
12	POSITION LIGHT	Replace	0	0

S.NO	PARTS PARTICULAR

Remarks **Approval subjected to policy term and condition, 64VB confirmation and NCB confirmation and pre-inspection or previous claim photographs.**

Note: ****Re-inspection is mandatory along with salvage.**
**** Approval is subject to policy terms & conditions**

Approved By: **Approver Contact No:**

For MOTORSATHI SERVICES

D-27, Shastri Nagar, Meerut, Utttar Pradesh, (250004) India
Email ID:: info@motorsathi.com| **Mobile No.**:+91 79410 50643