

WORK APPROVAL



Generated : 01-01-2026

| | | |
|---------------------|---------------------|----------------------|
| Claim Number | Insured Name | Workshop Name |
| CLM000202512145509 | ALOK KUMAR | USER1(SAMAHRAJGANJ) |

| | | | |
|-----------------------------|--------------------------------|--------------------------|---------------|
| Vehicle Number | New | Registration Year | 2025 |
| Chassis Number | MBLHAW469SHF01056 | Odometer reading | NIL |
| Vehicle Manufacturer | HERO MOTOCORP | Vehicle Model | SPLENDOR PLUS |
| Insurance Name | The Oriental Insurance Company | HUB Name | NIL |

| S.NO | PARTS PARTICULAR | REPLACE/REPAIR | LABOUR | PAINTING |
|------|----------------------|----------------|--------|----------|
| 1 | FRONT FENDER | Replace | 0 | 0 |
| 2 | LEVER CLUTCH | Replace | 0 | 0 |
| 3 | FORK PIPE RH | Replace | 0 | 0 |
| 4 | FORK PIPE LH | Replace | 0 | 0 |
| 5 | HANDLE PIPE | Replace | 0 | 0 |
| 6 | STEM COMP (HANDLE T) | Replace | 0 | 0 |
| 7 | FRONT VISOR | Replace | 0 | 0 |
| 8 | HEADLIGHT W/O BULB | Replace | 0 | 0 |
| 9 | ACCIDENTAL LABOUR | Repair | 500.00 | 0 |

| S.NO | PARTS PARTICULAR |
|------|------------------|
|------|------------------|

Remarks **Approval subjected to policy term and condition, 64VB confirmation and NCB confirmation and pre-inspection or previous claim photographs.**

Note: ****Re-inspection is mandatory along with salvage.**
**** Approval is subject to policy terms & conditions**

Approved By: **Approver Contact No:**

D-27, Shastri Nagar, Meerut, Utttar Pradesh, (250004) India
Email ID: info@motorsathi.com| **Mobile No.:**+91 79410 50643