

WORK APPROVAL



Generated : 01-01-2026

Claim Number	Insured Name	Workshop Name
CLM000202512145161	OM DIXIT	RENEWAL MOSARAM

Vehicle Number	UP31BU9622	Registration Year	2022-02-04
Chassis Number	MBLHAW113MHE61066	Odometer reading	NIL
Vehicle Manufacturer		Vehicle Model	SPLENDOR PLUS
Insurance Name	The Oriental Insurance Company	HUB Name	NIL

S.NO	PARTS PARTICULAR	REPLACE/REPAIR	LABOUR	PAINTING
1	SIDE COVER LEFT	Replace	0	0
2	FUEL TANK REPAIR	Repair	1400.00	0
3	HANDLE PIPE	Replace	0	0
4	ACCIDENTAL LABOUR	Repair	250.00	0
5	LEG GUARD	Replace	0	0

S.NO	PARTS PARTICULAR
------	------------------

Remarks **Approval subjected to policy term and condition, 64VB confirmation and NCB confirmation and pre-inspection or previous claim photographs.**

Note: ****Re-inspection is mandatory along with salvage.**
**** Approval is subject to policy terms & conditions**

Approved By: **Approver Contact No:**

For MOTORSATHI SERVICES

D-27, Shastri Nagar, Meerut, Utttar Pradesh, (250004) India
Email ID:: info@motorsathi.com| **Mobile No.:**+91 79410 50643