

WORK APPROVAL



Generated : 14-05-2026

| | | |
|---------------------|---------------------|----------------------|
| Claim Number | Insured Name | Workshop Name |
| CLM000202604149786 | ROHIT KUMAR | USER1(SAMAHRAJGANJ) |

| | | | |
|-----------------------------|--------------------------------|--------------------------|------------|
| Vehicle Number | UP56AZ1134 | Registration Year | 2024-04-19 |
| Chassis Number | MBLJFN35XRGC08126 | Odometer reading | NIL |
| Vehicle Manufacturer | | Vehicle Model | DESTINI |
| Insurance Name | The Oriental Insurance Company | HUB Name | NIL |

| S.NO | PARTS PARTICULAR | REPLACE/REPAIR | LABOUR | PAINTING |
|------|-------------------------|----------------|--------|----------|
| 1 | COVER PANEL UPPER FRONT | Replace | 0 | 0 |
| 2 | COVER FRONT PANEL LOWER | Replace | 0 | 0 |
| 3 | COVER FLOOR SIDE LH | Replace | 0 | 0 |
| 4 | PANEL INNER | Replace | 0 | 0 |
| 5 | ACCIDENTAL LABOUR | Replace | 200.00 | 0 |
| 6 | FRONT VISOR | Replace | 0 | 0 |

| S.NO | PARTS PARTICULAR |
|------|------------------|
|------|------------------|

Remarks **Approval subjected to policy term and condition, 64VB confirmation and NCB confirmation and pre-inspection or previous claim photographs.**

Note: ****Re-inspection is mandatory along with salvage.**
**** Approval is subject to policy terms & conditions**

Approved By: **Approver Contact No:**

D-27, Shastri Nagar, Meerut, Utttar Pradesh, (250004) India
Email ID: info@motorsathi.com| **Mobile No.:**+91 79410 50643