

# WORK APPROVAL



Generated : 14-12-2025

|                     |                     |                      |
|---------------------|---------------------|----------------------|
| <b>Claim Number</b> | <b>Insured Name</b> | <b>Workshop Name</b> |
| CLM000202512145161  | OM DIXIT            | RENEWAL MOSARAM      |

|                             |                                |                          |               |
|-----------------------------|--------------------------------|--------------------------|---------------|
| <b>Vehicle Number</b>       | UP31BU9622                     | <b>Registration Year</b> | 2022-02-04    |
| <b>Chassis Number</b>       | MBLHAW113MHE61066              | <b>Odometer reading</b>  | NIL           |
| <b>Vehicle Manufacturer</b> |                                | <b>Vehicle Model</b>     | SPLENDOR PLUS |
| <b>Insurance Name</b>       | The Oriental Insurance Company | <b>HUB Name</b>          | NIL           |

| S.NO | PARTS PARTICULAR                       | REPLACE/REPAIR | PAINTING |
|------|--|----------------|----------|
| 1    | No TCR parts applicable for this claim |                | 0        |

| S.NO | PARTS PARTICULAR |
|------|------------------|
|------|------------------|

**Remarks**                      **Approval subjected to policy term and condition, 64VB confirmation and NCB confirmation and pre-inspection or previous claim photographs.**

**Note:**                              **\*\*Re-inspection is mandatory along with salvage.**  
**\*\* Approval is subject to policy terms & conditions**

**Approved By:**                      **Approver Contact No:**

**For MOTORSATHI SERVICES**